

DEPARTMENT OF NATURAL RESOURCES DIVISION OF WATER RIGHTS

Norman H. Bangerter Governor Dee C. Hansen Executive Director
Robert L. Morgan
State Engineer State Engineer

Southern Area 130 North Main Street P.O. Box 563 Richfield, Utah 84701-0563 801-896-4429

May 7, 1990

LaVoy Utley 333 South US Highway 89 Sevier, Utah 84766

Dear Mr. Utley:

It has been brought to my attention by Ray Owens, Sevier River Commissioner, that the parshall flume at the head of the Wells Canal is in need of repair or replacement. In it's present condition, it is not possible to record accurately the amount of water flowing in the canal.

I would appreciate your immediate attention to this matter. Please contact Mr. Owens at 527-3269 as soon as possible to correlate with him a solution to this problem.

Sincerely,

M. Stanley Clams M. Stanley Adams, P.E.

Area Engineer

MSA/clw

cc: Ray Owens

Lee Sim